

CERTIFICATE OF COMPLIANCE

Certificate Number 20150220-R15140
Report Reference R15140-19991109
Issue Date 2015-FEBRUARY-20

Issued to: THE PLYCEM COMPANY INC
APDO POSTAL 1642-7050
CARTAGO COSTA RICA

**This is to certify that
representative samples of**

MINERAL AND FIBER BOARDS AND ROOFING
SYSTEMS

Mineral boards identified as "Fibrolit 100", "Plycem",
"Panelit", or "Plycem - Fibrolit".


Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 723, Test for Surface Burning Characteristics of Building
Materials
UL 790, Test Methods for Fire Tests of Roof Coverings
UL 263, Fire Tests of Building Construction and Materials

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at www.ul.com/contactus

